







KDP DG Metal Rack - Assembly Instructions


JOB 21611




Scan QR or Visit: displaybuilds.com/instructions_21611

A  Base 1	B  Side Frame 2
C  Shelf 5	D  Divider 5
E  Header Frame 1	F  Casters 4
G  Header POS 1	H  Side POS 2
I  M6 Bolt 40	J  M8 Bolt 8
K  Tool for M6 1	L  Tool for M8 1


1 Attach x4 (F) Casters to (A) Base with x16 (I) M6 Bolts using (K) Tool for M6.




2 Insert x2 (B) Side Frames into (A) Base and tighten with x8 (J) M8 Bolts using (L) Tool for M8.




3 Attach x5 (C) Shelves between both (B) Side Frames (starting from bottom towards the top) and tighten with x20 (I) M6 Bolts using (K) Tool for M6.




4 Insert x5 (D) Dividers into each (C) Shelf. Attach (E) Header Frame to both (B) Side Frames with x4 (I) M6 Bolts using (K) Tool for M6.



5 Slide (G) Header POS into (E) Header Frame, and slide x2 (H) Side POS into (B) Side Frames.



6 Assembly is completed.



! MISSING PARTS / DAMAGE CLAIM INSTRUCTIONS

- 1. Keep the box and packaging.** If items are damaged during shipping, photo evidence is required.
- 2. Photograph the box and markings.** Include a photo of the text on the box for all replacement part requests to ensure accurate identification.
- 3. Photograph the damage.** Photos of the damaged parts are required to process claims and expedite replacements. Retain the box, even if damaged.
- 4. Email your claim.** Send a description and the required photos to displaybuilds.com/contact or help@displaybuilds.com.